Appendix N	
Repeat perimeter photos 2010 and 2017	













June 2010



April 2017



















April 2017





April 2017

















Pre-Construction - June 2010 North Lateral Ditch and Double Wood Structure on Hobson-Struby Channel **Post-Construction - Dec. 2013** North Lateral Ditch and Double Wood Structure (continued)







Post-Construction - June 2013









Immediate Post-Construction - Oct. 2010 Hobson-Struby Confluence (looking upstream)









Post-Construction - June 2013







Post-Construction—May 2017

Post-Construction - Dec. 2013



Post-Construction - June 2010 Post-Construction - Jan. 2013 **Post Construction - June 2013 Post Construction - Dec. 2013** Hobson Cr. Wood Structure (looking upstream) Post-Construction—Sep. 2014 Post-Construction—Mar. 2016 Post-Construction—May 2017 Hobson Cr. Wood Structure (continued) Post-Construction - Sep. 2010 Post-Construction - Jan. 2013 **Post-Construction - June 2013 Post-Construction - Dec. 2013** Hobson-Struby Channel Plus Floodplain Wood Structure (looking upstream) Post-Construction - Sept. 2014 Post-Construction—Mar. 2016 Post-Construction—May 2017 Hobson-Struby Channel Plus Floodplain Wood Structure (continued)

Post-Construction - Sep. 2010 Post-Construction - Oct. 2010 Post-Construction - Jan. 2013 **Post Construction - June 2013** Double Wood Structure on Hobson-Struby Channel (looking downstream) Post-Construction - Dec. 2013 Post-Construction—Sep. 2014 Post-Construction—May 2017 Post-Construction—Mar. 2016 Double Wood Structure on Hobson-Struby Channel (continued) **During-Construction - Sep. 2010** Post-Construction - Oct. 2010 Post-Construction - Jan. 2013 **Post-Construction - June 2013** Double Wood Structure on Hobson-Struby Channel (looking upstream) Post-Construction - Dec. 2013 Post-Construction—Sep. 2014 Post-Construction—Mar. 2016 Post- Construction—May 2017 Double Wood Structure on Hobson-Struby Channel (continued)

Post-Construction - Oct. 2010 Post-Construction - Jan. 2013 **Post-Construction - June 2013** Post-Construction - Dec. 2013 Wood Structure on Lower Hobson-Struby Channel (looking upstream) Post-Construction—Sep. 2014 Post-Construction—Mar. 2016 Post-Construction—May 2017 Wood Structure on Lower Hobson-Struby Channel (continued) Post-Construction - Dec. 2013 Post-Construction - Oct. 2010 Post-Construction - Jan. 2013 **Post-Construction - June 2013** Hobson-Struby Channel Confluence With Tidal Channel (looking downstream) Post-Construction—Sep. 2014 Post-Construction—Mar. 2016 Post-Construction—May 2017 Hobson-Struby Channel Confluence With Tidal Channel (continued)

Confluence of E and E2 Tidal Channels (looking upstream)



Post-Construction - Aug. 2010









Post-Construction—Sep. 2014



Post-Construction—Mar. 2016



Post-Construction—May 2017

Post-Construction - Sep. 2014

Wood Structure at South End of the Old Hobson-Struby Ditch Fill










Post-Construction - May 2017



Beaver Dam constructed summer 2014 at confluence of channels C and F (paired images)



Beaver Dam constructed summer 2014 at confluence of channels C and F (continued)





Post-Construction - May 2017



Post-Construction - Sep. 2014



Post-Construction - May 2017



Post-Construction - Mar. 2016



Post-Construction - Mar. 2016

